



NOTICE TO MARINERS

NO. 2 (2017)

Arrival Procedures Cairnryan Port

All mariners are reminded to observe best practice and have appropriate manning and procedures in place when entering the limits of Loch Ryan and the Statutory Harbour Limits of the port of Cairnryan.

Vessels entering the Loch are required to confirm that to the best of their knowledge their bridge equipment and Propulsion and auxiliary machinery are in good working order to make a safe arrival to the berth.

Vessels are requested to confirm their status to Cairnryan Port Services when passing the Milleur buoy.

Mariners are reminded to keep Cairnryan Port Services apprised of any change in status of their equipment, deviation from their standard passage plan or any onboard emergency.

A Van Damme
Harbour Master
Port of Cairnryan Ltd

11 December 2017