



NOTICE TO MARINERS
07 (2018)

Berthing assessment Cairnryan

All vessels intending to berth at Cairnryan in winds exceeding 40knts have to confirm to CPS upon passing Forbes shoal that all machinery and berthing aids are in good working order and that the master has carried out a dynamic risk assessment on the prevailing weather conditions.

The Harbour master may issue direction to the vessel to hold off the berth until weather conditions have improved

This reporting requirement is in addition to the reporting described in NTM 02 (2017) .

For more information contact Cairnryan Port Services VHF CH14

A Van Damme
Harbour Master
Port of Cairnryan

16/01/2018