


## NOTICE TO MARINERS No 17 OF 2020

### Berth and Channel Depths



Following hydrographic survey of the port in March 2020, the below should be regarded as minimum depths:

**Main channel inward to No 2 buoy: 8.7m**

<b>Continental Quay</b>	<b>6.1m</b>	
<b>Chaine Quay</b>	<b>6.6m</b>	
<b>McKean Quay</b>	<b>6.5m</b>	6.4m patch 70m SE of M'Kean N dolphin
<b>Olderfleet Quay</b>	<b>5.4m</b>	
<b>Curran Quay</b>	<b>7.3m</b>	6.7m patch 60m E of Curran N dolphin

# **LARNE PORT**

**Notice to Mariners 19 of 2019 is subsequently cancelled.**

**For more information regarding these depths, please contact  
Larne Port Control.**

**Kind regards**

**Stuart Wilson  
Harbour Master  
LARNE PORT**

**Date:** 16<sup>th</sup> April 2020